







To be engaged in the person at machining industry for, repair grinding cutting tool is a technical ability that must want to master. No matter lathe jockey, milling machine jockey or bore bench work, passivation can appear inevitably after cutting tool uses period of time, numerical control machining center also is such. To do not affect production, or changes new cutting tool, or must undertake grinding a knife. Produce cost to reduce for the enterprise, general meeting asks operator adroitness grinds a knife, talk about the method grinding a knife of numerical control milling cutter next!

## The first pace, also be the most crucial make level area

When make level face, can do with a standard piece fiducial, cutting tool is ground in the blade on emery wheel hind, it is cutting tool on standard piece than be opposite the following, must planar make level, this is cutting tool whether the key that has ground, if pursue one:



The 2nd pace, open crossed slot

When opening crossed slot, the edge of both sides leaves to group in a line, groove leaves appreciably is a bit more greatly, better blade is ground from the back, if pursue 2:

