.

OF tool cutting cage angle of shallow killetalking about hill chooseaa

Kr of tool cutting edge angle (say to cut horny Entering Angleagain) the important parameter that is cutting tool, it is theincluded angle of cutting blade and feed direction, this parametercan affect the curly form that cuts bits greatly, decide the way ofcutting force.

Next graphs are the cutting sketch map of milling cutter ofcommonly used 90 degrees of tool cutting edge angle, this kindof cutting tool advocate cutting blade is side edge, use atmachining sidewall and the face with perpendicular underside, friend also calls square shoulder milling cutter. The appearance of bit has different design, the catling that includes strip piece, also have the 3 blade design that is a triangle roughly, also have the 4 blade design with quadrangular graphic representation. The direction that the characteristic when its are machined is cuttingforce is centered in radial, namely as perpendicular as cuttershaft direction, the cutting force of axes is smaller, can produce bigger curved moment to cutting tool, consequently multi-purposeat short imagine extended an use view. Bit also can do geminate face to design, such practicable point amounts are double, overall for, the double point razor blade of strip cuts late meeting effectively bigger, of the razor blade of 4 blade cut effectively deepa few smaller, at the same time the radial dimension of 4 blade razor blade is occupied bigger than comparing, the smallest diameter of corresponding arbor also can slant a few smaller, slope walks alongability to compare difference generally also to be done not have even.

Additional, part of highlight of graphic representation red is the cross section figure that cuts bits, assume rectangular position, the ply that cut bits just agrees with the every tine feed of cuttingtool. The ply that cut bits is the main referenced factor that bladepoint designs, razor blade of avery kind of has when the designbut the value of the ply that cut bits with the greatest susceptive, according to this the value pushs every tine feed in application.



10 degrees of tool cutting edge angle, gao Jin gives milling cutter

Summary: Above introduced the meaning of milling cutter tool cutting edge angle simply, brought