how to judge milling cutter to wear awaynor to know, how to judge milling cutter towear away, reach wear away means ofsettlementaa

Click upper part " mechanical design was connected " pay closeattention to us, learn a mechanical design everyday relevantknowledge dot

In the treatment of milling cutter, how choose reasonable millingcutter, seasonable judgement milling cutter wear away, canimprove treatment efficiency effectively not only, still can reducefinished cost.



Means of settlement of tatty of different situation cutting tool

1, point wears away



Improve way: Raise feed; Lower cutting rate; Use more the bitmaterial of wear-resisting is qualitative; Use coating razor blade.

2, collapse is broken

Improve way: The capable person with use nicer tenacity isqualitative; The razor blade of use point aggrandizement; Checkthe tigidity of machining complex;Increase tool cutting edgeangle.

3, heat is out of shape

Improve way: Lower cutting rate; Reduce feed; Decrease cut deep; Use the capable person that has hot rigid more to pledge.